

DONNING (S'HABILLER): IN HALLWAY

1. Hand rub



2. Gown



3. N-95 mask



4. N-95 fit check



5. Face shield



6. Gloves



7. Buddy check



DOFFING (SE DESHABILLER)

In antechamber:

1. Remove gloves



2. Hand rub



3. Remove gown



4. Hand rub



EXIT to Hallway:

1. Hand rub



2. Remove faceshield + place on wipes



3. Hand rub



4. Remove N-95 without touching!!



5. Hand rub

